

Approved For Release 2001/08/15 : CIA-RDP69B00041R002600090003-9

egy Signa - a summer ang	HOUR GENERATION CHECKLIST Applicate For Releas By 10 40041.	S: CIA-ROPES	3/1125 39/973300	260009090	(C) <b>3-9</b> 38	C. 12	7 23/	1145
ITEM	TASKS REQUIRED	H-HOUR START	H-HOUR COMP	ACTUAL	TIME COMP		CP CALLED	
		.74.77.6.4	OWN -	TIME COMP	PRI	SEC	PRI	SEC
2	MAINTENANCE ALERTED		H-24	0736				
3	DCM MEETING		H∞23	0830			14.71	1111
	MAINT SECURE NITROGEN, OXYGEN		H=23	0830				
5	PCL SECURE TRUCKS		H=23	0830		10 10 10 10	All the state of	1
	START MISSIGN AIRCRAFT PREFLICHT	H-22:30	H=00:30	0700	1/2			
6	RECEIVE FUEL LOAD FROM PLICHT PLANNING		H-22:30	0900		ومعرر		
7 8	RECEIVED 25X1A TEB AND REFUEL		H-22	0930				
		H-22	H=19	1235	1400	1800	1440	2100
9	ARC-50 CCDES RECEIVED		H-22	6335			3714	
20	COMMO AND IFF PREFLIGHT	H=-22	H=18	1335	1100	1415		Part <b>≠</b> m
11	SELECT RECOVERY CREW AND GIVE TO DOM	H- 20	H-16	1925	1100	A THE PROPERTY.	¥:4	
	Ins Pristlight	125.15	F≔Ló	1935	1130	L.	or near orners independ the last page	
20	TO 17 - 10 - 10 - 10 - 10 - 10 - 10 - 10 -	H-16	12-13		1530			
14	Package David appreciation		11-13:45					
	PACEAGE LOADED (GALL SECURITY BEFORE MOVING PACEAGE)	]L-12	#=08:30	9328	War barre	2030		2100
16	SIP AND SYSTEM VI CHECKOUT	H-J1		933	West for his one of the second state of the se	To remain the same of the same	Fisher Fri 1240	
17	POL SEND 25X1A			2049	los or every	3 - L - 11 <b>4</b>		
18	LOX TOP OFF	H=4	H=03:30	6488				
19	NITROGEN TOP OFF	H=4.	H=03:30	0166	1060	2000		
50	AIRCRAFT STATUS BRIEF: CC, INS, EWS, PKG & DCM	ii-03:30	The state of the s	8 725 8 730		000	41.05	
21	START INS WARMUP	11-05150		0755			<b>F</b>	
22	INSTALL CSC MAGAZINE IN NOSE	U 02.20	H=03:30	0835	THE OWNER AND DESCRIPTION OF STREET		Market Mark	Restanda.
?3	INS DATA TAPE LOADING	H=03:30	H=3	0935	ATTIVITY OF THE SECOND			
-	PACKAGE I HELIUM PURGE Q-BAY	H-02:30	THE RESERVE THE PERSON NAMED IN	1055				
arm committee	PERSONAL EQUIPMENT LOADED	H-2	H=00:30	11925				
	MAINT CALL SECURITY TO STERLIZE COCKPIT	H-02:15	H-2	0530	4.7			<b>11.8</b>
Secretaria de Maria	COCKPIT SET UP PER CODE SHEET	H=2	H-01:50	0235				
			H-01:50	0935				<b>124</b> 2
9	VIEWFINDER LOADED WITH FILM Approved For Release 2001/08/15 ENGINEER CHECK AIRCRAFT	CHA-CADR69	300041R00	2 <b>600000</b> 00			e North	44.4
7/79/2020	A STATE OF THE POLICY OF THE P	II=01:30	Hel	1025	de la companya de la			

	i Tasks required	H=HOUR TART	H-HCUR COMP	actual TIME COMP	TIME COMP		C.P. CALLED	
TE					PRI	3EC	PRI	SEC
0	ENGINE START		H-00:30	0730				
1	TAXI		H=00:20	6715		Logical Street	in Alaka Kecama	
2	RECOVERY GEAR IN PLACE		H+1	6335			taria.	
_			1 (N. 20) 4 /r					
4	POST MISSION LANDING CHECKLIST							market and the second
ì	LAND AND CCCL AIRCRAFT	I+00:00	L+00:30					
5	SECURE ACFT AND SERVICE ENG GIL	I.+00:30	I+01:15			A SHARE		La la
3	REACVE SORE TAPE AND GIVE TO SIP	L+0030	L+Cl:15			en en Cantigge San 2 Mari Se	146	
4	REMOVE VIEWFINDER FILM STRIP AND MAPS	L+00:30	1.401:15			operation of		
5	REMOVA BLUE EXIG TAPE	I+00:30	1:101:15		And the second s	The state of the s		THE RESERVE OF
6	RAINTUNANCE DESKIEF	1+00:45	1+01:15			7	to the same of the	1 100
5	REMOVE INSTRUMENTATION PACKAGE	L+01:00	1401:15		which is not being the special of th	1 Property	The second second	The second second with the second sec
8	MOVE ARTICLE INTO HANGAR	I#01:15	1+01:30	Marie en	Retractions		in kredak	ar negret
	DOWNLOAD PKG (NOTIFY SECURITY TO CLOSE HANGAR DOORS)	i#03:30	1+02:30	1	•	1	Sales Associate	100 TO 100 TO 100
C	SCEW DATA TO DOOM FOR 25X1A		I+03:30	* 01-00-10-10-10-10-10-10-10-10-10-10-10-1		Carlos es	4,00	***
1	SIP DATA TO DCO		I+04:15					
2	"TAKE" TO SUPPLY (NOTLEY SECURITY BEFORE MOVING TO SUPPLY)	W ValVerbushikasharman alban	1+05:00			-		
3	PACKAGE SUBMIT 25X1A	The state of the s	L+05:00					
4	BD II TAPE TO SECURITY		L+05:00					24 A
5	INS/SCDM TAB RUN TO SECURITY		L+05:00		Continue 2 hour		124	
6	SCDM TAPE TO SECURITY		1+09:00	V-V-L-V-				
7	ING SUBMIT 25X1A		I+10:00					



## 

